

Work Order ID 94408

Monday, December 17, 2012 9:19:06 AM

94408

Ship Today

Page 1

Item ID: D350-727-045

Accept

N900040100

Setup

Start

NS1

Revision ID:

Item Name: Wearplate, Full Length, LH/RH

Stop

NS2

Start Date: 12/17/2012 Start Qty: 4.00

4

Cust Item ID:

Required Date: 12/17/2012 Req'd Qty: 4.00

4

Customer:

Reference:

Approvals: Process Plan: MF

Date: 12-17

Tooling:

Date:

Run

Start

NR1

QC:

Date:

SPC (Y/N):

Date:

Stop

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
IIN D350-727	Rev A

100

100

DC

Document Control

DOCUMENT CONTROL

0.00

DAS
15
8-89

b12-17

4 12/17/12-17

(4)

110

110

Packaging

Packaging

Pick Kit

0.00

Memo

0.00

12/17/12 (4) 8

120

120

QC

Quality Control

QC4- 100% Inspect kits for completeness

0.00

DAS
15
8-89

b12-17

4

Work Order ID 94408

Monday, December 17, 2012 9:19:06 AM

94408

Page 2

Item ID: D350-727-045

Accept

N900040100

Setup

Start

NS1

Revision ID:

Item Name: Wearplate, Full Length, LH/RH

Stop

NS2

Start Date: 12/17/2012 **Start Qty:** 4.00

4

Cust Item ID:

Required Date: 12/17/2012 **Req'd Qty:** 4.00

4

Customer:

Reference:

Approvals:	Process Plan:	Date:	Tooling:	Date:	Run	Start	*NR1*
	QC:	Date:	SPC (Y/N):	Date:		Stop	*NR2*

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 *130* Packaging	Packaging	0.00	<i>Ship</i>			4	18/18/17		<i>DAS 20 9-6</i>
Packaging	Memo	0.00							
	Identify and pack for shipping as per PPP D350-727-045 Location: _____ PPP Rev: _____								

140 *140* QC	QC21- Final Inspection - Work Order Release	0.00	<i>12/12/17</i>
Quality Control	Memo	0.00	<i>MF 12-12-17</i>

